

WILLIAMS STREET - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W-S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans
		Α	Υ	Older one way ADA ramp across Williams; no DWS	Partial	Review for Phase IV work. No crosswalk across No. Washington at this point - ramp aligned to cross Williams only; no DWS
Williams	1		Υ	Older sidewalk, some pitting on surface	Partial	
		С	Υ	Sidewalk is in fair shape. It slopes until it is at grade with the adjoining pavement	Partial	
		В	Y	There is a one-way ramp to cross Williams but no DWS texture. No Ramp to cross No. Washington	Partial	Review for work in Phase IV
Williams	2		Υ	There is new sidewalk extending approximately 8' along Williams that terminates in a DWS that is blocked by a pole	Partial	Pole for the town lot fence is located in the center of the DWS. The short sidewalk is OK, but not long enough & its ramp ends in a pole.
		D	R	Sidewalk does not extend to a logical end-of-block corner	No	Dangerous conflicts between town lot, tractor trailer parking and pedestrians
		E	R	No improvements	No	
Williams	3		R	No improvements	No	
		G	R	No improvements	No	
		F	R	No improvements	No	
Williams	4		R	No improvements except a wooden pedestrian bridge across the run	No	
		Н	R	Cracked and broken sidewalk wraps around Harrision on to Williams	No	Sidewalk extension from Harrision is even with the pavement and in poor condition
		Ĺ	R	No improvements	No	
Williams	5		R	No improvements	No	Dangerous area for pedestrians
		К	R	No improvements	No	Dangerous area for pedestrians
	9					

Identification & Coding of Sidewalks & Corners



Color Coding of Results



WILLIAMS STREET - TOWN OF BATH SIDEWALK EVALUATION

PHOTOS OF SPECIFIC AREAS

