

South Washington Street - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Evaluated Condition Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W/S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans

Overall Note for this Street: With the exception of the ADA ramps at Fairfax St, there are no painted cross-walks that cross South Washington Street between Fairfax St and Martinsburg Rd (Rte-9) and all ramps are one-way aligned with S/W only

		A	G	New 2-way Ramps - done in Phase 3	Yes	Ramps; materials and Detectable Warning System intact; Adjacent Traffic light/crossing system appears to be ADA compliant
South Washington	1		G	Appears that S/W surface has been "blasted" or otherwise treated to make it rougher; otherwise OK	Yes	
		C	Y	Sidewalk & driveway to Park are essentially level - no ramp present	Partial	There is no Detectable Warning System (DWS) at this corner
		B-1	G	New 2-way Ramps - done in Phase 3	Yes	Ramps; materials and Detectable Warning System intact; Adjacent Traffic light/crossing system appears to be ADA compliant
South Washington	2a		G	Wide sidewalk; Good to Fair surface	Yes	Some small "steps" between sections
		B-2	Y	Narrow Ramp (3.5 ft)	Partial	No DWS at ramp
		D-1	Y	Sidewalk is essentially level with the street crossing	Partial	No ADA features at this corner; no DWS
South Washington	2b		G	Fair to good surface.		Some small "steps" between sections
		D-2	Y	Narrow Ramp (xxx? ft)	Partial	No DWS at ramp
		E	R	No Ramp present & S/W is only 3 ft wide to Fence	No	Estimate S/W not useable for ADA since only one end has access via level drive & S/W
South Washington	3		R	S/W is only 3 ft wide to Fence	No	Possible ADA access at only One End; no DWS at either end
		G	R	Slight access since drive & S/W are almost level	No	No DWS; possible "trap" since there is no Ramp at other end of section "3"
		F	R	Narrow Ramp (3 ft)	Partial	No DWS at ramp
South Washington	4		G	Fair to good surface - some small steps	Yes	
		(2) Ramps to CNB Driveway	Y	S/W Ramps to CNB Parking Lot - narrow but in-line with S/W	Partial	No DWS at ramps
		H	Y	Wider Ramp almost 4 ft	Partial	No DWS at ramp
		I	R	S/W is level with street area; but no ramp or DWS	No	No DWS
South Washington	5		R	S/W is lower than street; prone to flooding and dirt build-up; eroded, cracked & broken	No	S/W not always level and sometimes pitched; poor condition
		K	R	No Ramp	No	No DWS

South Washington Street - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Evaluated Condition Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W-S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans
		J	Y	Narrow Ramp	Partial	No DWS
South Washington	6		G-Y	Fair to good surface with only some erosion	Yes	The 100 ft South of Market St has some erosion and cracks and small steps.
		L	R	No Ramp; Electric/Phone Pole at corner; gravel "ramp" around pole gets "ramp-like" access to Warren St.	No	
		M	R	No Ramp	No	No DWS
South Washington	7		G	Fair to Good surface	Yes	
		O	G	Ramps to driveway look OK	Partial	No DWS
		N	R	No Ramp & No DWS	No	
South Washington	8		Y	S/W surface generally OK, but ends abruptly with poor surface at gas station pavement		
		P	R	About 1/2 of this block is paved as gas station access. There are no curbs, S/W or painted areas near gas station to point out any ADA access here		


South Washington Street - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Evaluated Condition Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W-S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans

Identification & Coding of Sidewalks & Corners

Sidewalk Assessment by Streets & Blocks


Street: South Washington St (Fairfax to Martinsburg Rd (Rte-9))



South Washington Street - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Evaluated Condition Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W-S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans

Color Coding of Results



South Washington Street - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Evaluated Condition Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W-S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans

PHOTOS OF SPECIFIC AREAS



