

FAIRFAX STREET - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Evaluated Condition Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W-S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans
		A	Y	Sidewalk at Park Entrance has been modified with asphalt paving and asphalt berm. This berm prevents ADA wheelchair access to the Park and the History Museum from across Fairfax St	No	A low curb on the north side of Fairfax, flush with new street paving blocks; hints at ADA access to the Park entrance across Fairfax St; but the berm on the south side prevents such access. See Photos
Fairfax	1		G	Sidewalk in good shape to museum; remainder narrow and needs improvement	Yes	The majority of the sidewalk to the west end of park in great shape. Completed in Phase 3
		C	G	Two way ramps; recently installed	Yes	Completed in Phase 3.
		B	G	No ramp on Fairfax, but one-way ramp just around corner on Wilkes St, across from town building	Yes	No ramp to cross Fairfax directly, but new ramp at Wilkes St. Completed in Phase 3
Fairfax	2		G	Oversized sidewalk; recently improved	Yes	Completed in Phase 3.
		D	G	Two way ramps recently installed	Yes	Completed in Phase 3.
		E	G	Two way ramps; recently improved	Yes	Completed in Phase 3.
Fairfax	3		Y	Wide sidewalk, cracked in areas where driveways cross the sidewalk	Partial	Although sidewalk generally good; driveway crossings cracked. Drainage issues in this area. Considered for work in Phase 4.
		G	G	Two way ramps; recently improved	Yes	Completed in Phase 3.
		F	G	Two way ramps; recently improved	Yes	Completed in Phase 3.
Fairfax	4		G	Sidewalk ADA compliant	Yes	
		H	G	Two way ramps; recently improved	Yes	Completed in Phase 3.
		I	G	Two way ramps, recently improved	Yes	Completed in Phase 3.
Fairfax	5		G	Sidewalk width and condition good	Yes	
		K	R	Sidewalk is flush with pavement on Green St.	No	
		J	G	Two way ramps, recently improved	Yes	Completed in Phase 3.
Fairfax	6		G	Sidewalk is wide and in good condition	Yes	
		L	R	Stairs bring sidewalk to Green St.	No	See Picture


Identification & Coding of Sidewalks & Corners

### Sidewalk Assessment by Streets & Blocks

#### Fairfax St (Wilkes to N. Green St)

**Key:**

- Red Letters are Street/Sidewalk Corners
- Blue Numbers are Sidewalks along the Street




Color Coding of Results

Sidewalk Assessment by Streets & Blocks






Fairfax St (Wilkes to N. Green St)

Key:

Red Letters are Street/Sidewalk Corners  
Blue Numbers are Sidewalks along the Street



PHOTOS OF SPECIFIC AREAS



FAIRFAX STREET - TOWN OF BATH SIDEWALK EVALUATION


PHOTOS OF SPECIFIC AREAS - IMPROVED BY STREETSCAPES AND OTHER PROJECTS




Sidewalk "4" Looking East adjacent to Court House



Sidewalk "4" Looking West adjacent to Court House



Sidewalk "6" & Corners "H" & "J" Looking West adjacent to C of C Office



Corners "D" & "F" Looking West at No. Washington St.



Sidewalk "2" Looking West at No. Washington St.



Corner "C" Looking South at Park Entrance at No. Washington St.

