

LIBERTY ST - TOWN OF BATH SIDEWALK EVALUATION

Street	Sidewalk Map No.	Corner Map Letter	Evaluated Condition Code	Condition Found (Missing Sections; warped; steps/drops; patches; <4 ft wide)	Complies w/ADA Stds?	Notes
	1, 2, 3 etc	A, B, C etc	G-Y-R	MS-W-S/D-P-<4'	Ramps/Material	Status in Streetscapes Plans
		A	R	No improvements. This portion of Liberty is incorporated into the State Park as driveway and parking.	No	Note: Appears accessible but there are no markings to assist. Because there are no sidewalks there is potential for conflicts with vehicles
Liberty St	1		R	No improvements. This portion of Liberty is incorporated into the State Park as driveway and parking.	No	Note: Appears accessible but there are no markings to assist. Because there are no sidewalks there is potential for conflicts with vehicles
		C	R	Narrow ramp connecting to a 3' sidewalk; no landing; no DWS	No	It doesn't meet ADA standards and is a sloping access to the pavement
		B	R	No improvements. This portion of Liberty is incorporated into the State Park as driveway and parking.	No	Note: Appears accessible but there are no markings to assist. Because there are no sidewalks there is potential for conflicts with vehicles
Liberty St	2		R	No improvements. This portion of Liberty is incorporated into the State Park as driveway and parking.	No	Note: Appears accessible but there are no markings to assist. Because there are no sidewalks there is potential for conflicts with vehicles
		D	Y	One way ramp to cross Liberty; no DWS. Ramp is worn and pitted	No	Ramp is south of the crosswalk
		E	R	One way ramp to cross Liberty; no DWS	No	
Liberty St	3		R	No improvements. Parking backs out on to Liberty		Parking meters line the south side of the street
		G	R	No Improvements.	No	
		F	Y	One way ramp to cross Washington; no DWS	No	Access aligned with sidewalk
Liberty St	4		G	Sidewalk from Washington to the east side of the church in great shape; Stairs to Green are not ADA compliant	Partial	
		H	R	Sidewalk landing connects to substandard sidewalk in front of church's social service building.	No	Sidewalk landing is a little below the grade of Green St

LIBERTY ST - TOWN OF BATH SIDEWALK EVALUATION


Identification & Coding of Sidewalks & Corners

Sidewalk Assessment by Streets & Blocks

Street: Liberty St (End to End)



Key:
Red Letters are Street/Sidewalk Corners
Blue Numbers are Sidewalks along the Street




LIBERTY ST - TOWN OF BATH SIDEWALK EVALUATION

Color Coding of Results

Sidewalk Assessment by Streets & Blocks

Street: Liberty St (End to End)



- Key: *
- Green – Near-new/new condition; meets ADA Criteria (also completed Streetscapes Phase)
 - Yellow – S/W & Corner with some patches/steps/erosion; serviceable; not fully up to ADA Criteria
 - Red – Poor condition, materials; major patches, steps and drops; not ADA compliant

LIBERTY ST - TOWN OF BATH SIDEWALK EVALUATION

PHOTOS OF SPECIFIC AREAS

