

Berkeley Springs State Park Work-In-Progress Photos

Repaired Stone Walls of the Run



West Wall

East Wall

**Both Walls – Looking South
toward Country Inn Bridge**



East Wall



**West Wall with Repair after Removal of
North Bridge**

Berkeley Springs State Park Work-In-Progress Photos

Removing the South Bridge



**The New South Bridge at the Factory
Prior to final Black Powder Coat and Decking**



**New West Side Abutment
for New South Bridge
(Behind new stone wall)**

Berkeley Springs State Park Work-In-Progress Photos



Bridge Sawed in Half – Excavator Could not Break It Free



**Chains from Excavator being Connected to Outer Edge to
“Lever Up” and Pull Bridge**

Removing the North Bridge



**The Reason the Bridge was so Hard to Remove
(Concrete Deck Strengthened by Internal Railroad Rails)**

Berkeley Springs State Park Work-In-Progress Photos

New Colored and Stamped Concrete Sidewalks



**Example of Curved Area Edge Stamping
at Sidewalk Intersection
(Cleaning & Sealing not yet done)**



Close-up Near Fairfax St (still wet)



**East of Run Sidewalk Looking South from Fairfax St
(Section nearest camera is still wet (dark) from washing and
sealant)**